UST Service Provider List (All) - Le	k Detection Testing Companies Only
--------------------------------------	------------------------------------

Company			Listing Submitted		Area of state conducts work	
Petroleum Equipment Service of Wilson, Inc.		Phone	(252) 237-6047		Coastal (East of I-95): Yes	
PO Box 502		Fax	(252) 237-5507		Central (West of I-95 and East of I-77): Yes	
711 S. Goldsboro St.		· ux	(222, 23. 333.		Mountains (West of I-77): No	
Wilson, NC 27893	V	<b>Vebsite</b>	www.peswilson.com		mountains (west of 1-77). No	
Comp	oliance Tes	ting and	Monitoring		<b>UST Equipmment Service Contractors</b>	
Automatic Line Leak Detector Testing:	No		Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u>		cal Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No		evention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	No		ghtness Testing:	No	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	No		ernal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	No	UST Int	ernal Lining Inspections:	No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	No	Other:			UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	No				UST System Removal:	<u>Yes</u>
Er	nvironment	al Servic	ce Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Co	ompliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Eq	uipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste [	Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:				
Soil and Water Testing Lab:	No					
Company			Listing Submitted	2/1/2021	Area of state conducts work	
Advanced Environmental Solutions, LLC		Phone	(828) 664-9822		Coastal (East of I-95): Yes	
P.O. Box 1426		Fax	(866) 425-2661		Central (West of I-95 and East of I-77): Yes	
Black Mountain, NC 28711		I ux	(000) 420 2001			
	V	<b>Vebsite</b>	advancedenvironmentalsolutions.com		Mountains (West of I-77): Yes	
Comp	oliance Tes	ting and	Monitoring		<b>UST Equipmment Service Contractors</b>	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill	Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u>	Statistic	cal Iventory Reconciliation Services:	<u>Yes</u>	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Pre	evention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Ti	ghtness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:		LICTIM	ernal Inspections (Integrity Assessments):	NI-	UST Equipment Repair:	No
Corrosion Protection System Testing.	<u>Yes</u>	UST IN	ernar mopeonorio (miegrity 7.00000memo).	No		
Leak Detection Equipment Operability Check:	<u>Yes</u> <u>Yes</u>		ernal Lining Inspections:	No	UST System Installation - Complete Systems:	No
					UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No
Leak Detection Equipment Operability Check:	Yes	UST Int				
Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	<u>Yes</u> No	UST Int Other:	ernal Lining Inspections:		UST Piping/Sump Installation:	No
Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes No Yes	UST Into	ernal Lining Inspections:		UST Piping/Sump Installation: UST System Removal:	No
Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes No Yes nvironment	UST Into	ernal Lining Inspections:	No	UST Piping/Sump Installation: UST System Removal:	No
Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Energency Cleanup - Spill/Release:	Yes No Yes nvironment No No	UST Into Other: tal Service UST Co UST Eq	ce Firms compliance Consultants:	No No	UST Piping/Sump Installation: UST System Removal:	No
Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Yes No Yes nvironment No No	UST Into Other: tal Service UST Co UST Eq	ce Firms  pmpliance Consultants: quipment Verification:	No No No	UST Piping/Sump Installation: UST System Removal:	No

UST Service	se Pro	ovider List (All) - Leak Detection	i esting C	companies Only	
Company		Listing Submitted	5/17/2021	Area of state conducts work	
AES of Greenville LLC		Phone (252) 758-3311		Coastal (East of I-95): Yes	
141 S. Market Street		Fax (252) 481-5814		Central (West of I-95 and East of I-77): Yes	
Washington, NC 27889		· · ·		Mountains (West of I-77): Yes	
		Website www.aes-nc.com		mountains (troot of 177).	
Comp	oliance Te	esting and Monitoring		<b>UST Equipmment Service Contractors</b>	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	<u>Yes</u>	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	<u>Yes</u>	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	<u>Yes</u>
Er	nvironme	ntal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	4/15/2021	Area of state conducts work	
American UST Compliance Testing		Phone (919) 777-8543		Coastal (East of I-95): Yes	
180 BPW Club Rd. A-1		Fax		Central (West of I-95 and East of I-77): Yes	
Carrboro, NC 27510				Mountains (West of I-77): Yes	
		Website		mountains (West of 1-77).	
Comp	oliance Te	esting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Provention Equipment Operability Cheeks	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
ratemane into leant between reemig.	100	Overfill Prevention Equipment Operability Check:	100		
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	No No	Leak Detection Equipment Installation Servicing:	No
<u> </u>				Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	No		
Containment Sump Testing: Corrosion Protection Design Experts:	<u>Yes</u> No	Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No <u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u> No
Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	<u>Yes</u> No No	Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No <u>Yes</u> <u>Yes</u>	Spill Bucket Installation Repair: UST Equipment Installation - Other:	<u>Yes</u> No
Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	Yes No No Yes	Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No <u>Yes</u> <u>Yes</u> No	Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	<u>Yes</u> No <u>Yes</u>
Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Yes No No Yes Yes	Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No <u>Yes</u> <u>Yes</u> No	Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	Yes No Yes No
Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes No No Yes Yes No Yes	Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No <u>Yes</u> <u>Yes</u> No	Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	Yes No Yes No No
Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes No No Yes Yes No Yes	Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No <u>Yes</u> <u>Yes</u> No	Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes No Yes No No
Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes No No Yes Yes No Yes	Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No Yes Yes No No	Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes No Yes No No
Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Er Emergency Cleanup - Spill/Release:	Yes No No Yes Yes No Yes No Yes No Yes No	Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  ntal Service Firms UST Compliance Consultants:	No Yes Yes No No	Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes No Yes No No

Oil and Solvent Recycling:

Soil and Water Testing Lab:

No

No

Other:

UST Service Provider List (All) - Le	k Detection Testing Companies Only
--------------------------------------	------------------------------------

Company		Listing Submitted		Area of state conducts work	
Bay Compliance and Testing LLC	Ph	none (757) 410-5974		Coastal (East of I-95): Yes	
P.O. Box 16628		Fax		Central (West of I-95 and East of I-77): No	
Chesapeake, VA 23328				Mountains (West of I-77): No	
	Web	site <a href="https://baycomplianceandtesting.com/">https://baycomplianceandtesting.com/</a>		Wouldains (West of 1-77). No	
Comp	oliance Testing	g and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:		verfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:		tatistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:		pill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:		ank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:		ST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:		ST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No O	ther:		UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	No
Er	nvironmental S	Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No U	ST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No U	ST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No W	/aste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No O	ther:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	7/30/2020	Area of state conducts work	
Blue Ridge Geological Services, Inc.	Ph	none (336) 382-6849		Coastal (East of I-95): Yes	
7356 Belmont Drive		Fax		Central (West of I-95 and East of I-77): Yes	
Trinity, NC 27370				Mountains (West of I-77): Yes	
	Web	site <u>www.blueridgegeo.com</u>		Modificants (West of 1-11). 163	
Comp	oliance Testing	g and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No O	verfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No S	tatistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No S	pill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No Ta	ank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No U	ST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No U	ST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No O	ther:		UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	No
		Corvino Eirmo		Other:	
Er	nvironmental S	Dervice Firms			
Emergency Cleanup - Spill/Release:		ST Compliance Consultants:	<u>Yes</u>		
	Yes U		<u>Yes</u> No		
Emergency Cleanup - Spill/Release:	Yes U	ST Compliance Consultants:			
Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Yes U Yes U Yes W	ST Compliance Consultants: ST Equipment Verification:	No		

UST Servi	ce Prov	vider List (All) - Leak Detection	on Testing (	Companies Only	
Company		Listing Subm			
Bunnell-Lammons Engineering, Inc.		Phone (828) 277-0100		Coastal (East of I-95): Yes	
130 Oval Road		Fax (828) 277-0110		Central (West of I-95 and East of I-77): Yes	
Arden, NC 28704		,		Mountains (West of I-77): Yes	
	1	Website www.blecorp.com		mountains (West of 177). 163	
Comp	pliance Tes	ting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	<u>Yes</u>	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	<u>Yes</u>	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	No
E	nvironmen	tal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	ı <u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	No	Other: Trust F	Fund Projects		
Soil and Water Testing Lab:	No				
Company		Listing Subm	itted 5/14/2021	Area of state conducts work	
Cobb Environmental & Technical Services, Inc	c.	Phone (662) 841-0995		Coastal (East of I-95): Yes	
P. O. Box 1602, Tupelo, MS 38802		Fax (662) 841-0810		Central (West of I-95 and East of I-77): Yes	
871 South Green Street		` '		Mountains (West of I-77): Yes	
Tupelo, MS 38804	\	Website <u>www.cobbenv.com</u>		mountains (West of 177).	
Comp	pliance Tes	ting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
		Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection Design Experts:	No	- h	100		
Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No <u>Yes</u>	Tank Tightness Testing:	No No	UST Equipment Installation - Other:	<u>Yes</u>
			No	UST Equipment Installation - Other: UST Equipment Repair:	<u>Yes</u> Yes
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	No		
Corrosion Protection System Repairs: Corrosion Protection System Testing:	<u>Yes</u> <u>Yes</u>	Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No	UST Equipment Repair:	Yes
Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	<u>Yes</u> <u>Yes</u> <u>Yes</u>	Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No	UST Equipment Repair: UST System Installation - Complete Systems:	Yes Yes
Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes Yes Yes Yes No	Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No	UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	Yes Yes Yes
Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes Yes Yes Yes No	Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No	UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes
Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes Yes Yes Yes No	Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No	UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes
Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Emergency Cleanup - Spill/Release:	Yes Yes Yes Yes No No No No	Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:  tal Service Firms UST Compliance Consultants:	No No No	UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes

Oil and Solvent Recycling:

Soil and Water Testing Lab:

No

No

Other:

UST Service Provider List (All) - Leak Detection Testing C	Companies Only

Company			Listing Submitted	12/30/2021	Area of state conducts work	
Crompco, LLC	Р	hone (610) 278-7203			Coastal (East of I-95): Yes	
1815 Gallagher Road		Fax (610) 278-7621			Central (West of I-95 and East of I-77): Yes	
Plymouth Meeting, PA 19462		(010) 210 1021			Mountains (West of I-77): Yes	
	We	bsite <u>www.crompco.com</u>			Wouldains (West of 1-11). Tes	
Comp	pliance Testin	g and Monitoring			<b>UST Equipmment Service Contractors</b>	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Op	perability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	Yes S	Statistical Iventory Reconciliation	Services:	<u>Yes</u>	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No S	Spill Prevention Equipment Testi	ing:	<u>Yes</u>	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No 7	Tank Tightness Testing:		<u>Yes</u>	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	<u>Yes</u>	JST Internal Inspections (Integrit	ty Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	JST Internal Lining Inspections:		No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	Yes (	Other:			UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>				UST System Removal:	No
Er	nvironmental	Service Firms			Other:	
Emergency Cleanup - Spill/Release:	No l	JST Compliance Consultants:		<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No l	JST Equipment Verification:		Yes		
Environmental Engineer/Geologist Soil and GW Cleanu	ı No \	Waste Disposal and Treatment:		No		
Oil and Solvent Recycling:	No (	Other:				
Soil and Water Testing Lab:	No					
Company			Listing Submitted	9/24/2021	Area of state conducts work	
C-Store Services, Inc.	Р	hone (919) 662-0798			Coastal (East of I-95): Yes	
7129 Hidden Valley Trail		Fax (919) 662-0711			Central (West of I-95 and East of I-77): Yes	
Garner, NC 27529		1 dx (313) 002-0711				
	We	bsite			Mountains (West of I-77): No	
Comp	oliance Testin	g and Monitoring			<b>UST Equipmment Service Contractors</b>	
Automatic Line Leak Detector Testing:	No (	Overfill Prevention Equipment Op	perability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	Yes
Containment Sump Testing:	Yes S	Statistical Iventory Reconciliation	Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No S	Spill Prevention Equipment Testi	ng:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	No 7	Tank Tightness Testing:		No	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	No l	JST Internal Inspections (Integrit	ty Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	No l	JST Internal Lining Inspections:		No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No (	Other:	UST-27 monthly insp	pection	UST Piping/Sump Installation:	<u>Yes</u>
S S S S S S S S S S S S S S S S S S S					LICT Custom Democrats	<u>Yes</u>
Line Tightness Testing:	No				UST System Removal:	
Line Tightness Testing:	No	Service Firms			Other:	
Line Tightness Testing:	No nvironmental			No		
Line Tightness Testing:  Er  Emergency Cleanup - Spill/Release:	No nvironmental No	JST Compliance Consultants:		No No		
Line Tightness Testing:	No nvironmental No U					
Line Tightness Testing:  Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No nvironmental No (	JST Compliance Consultants: JST Equipment Verification:		No		

UST Service Provider List (All) - Le	k Detection Testing Companies Only
--------------------------------------	------------------------------------

Company	oo i ioviac		Listing Submitted		Area of state conducts work	
Environmental Laboratories, Inc	Ph	one (864) 370-			Coastal (East of I-95): Yes	
PO Box 1729		Fax (864) 752-			Central (West of I-95 and East of I-77): Yes	
Travelers Rest, SC 29609		(301) 702			Mountains (West of I-77): Yes	
	Webs	site <u>www.elabs</u>	sinc.net		Mountains (West of 1-77). Tes	)
Comp	oliance Testing	and Monitoring	J		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:			quipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:			econciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:		ill Prevention Equi		<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:		nk Tightness Test	_	<u>Yes</u>	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	Yes US	T Internal Inspect	ions (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	Yes US	T Internal Lining I	nspections:	<u>Yes</u>	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	<u>Yes</u> Ot	ner:			UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	<u>Yes</u>				UST System Removal:	<u>Yes</u>
Er	nvironmental S	ervice Firms			Other:	
Emergency Cleanup - Spill/Release:	No US	T Compliance Co	nsultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No US	T Equipment Veri	fication:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No W	aste Disposal and	Treatment:	No		
Oil and Solvent Recycling:	No Ot	ner:				
Soil and Water Testing Lab:	No					
Company			Listing Submitted	10/26/2021	Area of state conducts work	
Guardian Fueling Technologies	Ph	one (919) 729-	6980		Coastal (East of I-95): Yes	;
5116 Departure Drive		Fax (919) 769-	2919		Central (West of I-95 and East of I-77): Yes	;
Raleigh, NC 27616					Mountains (West of I-77): No	
	Webs	site www.guar	dianfueltech.com		mountains (West of 177). No	
Comp	oliance Testing	and Monitoring	]		<b>UST Equipmment Service Contractors</b>	
Automatic Line Leak Detector Testing:	No Ov	erfill Prevention E	quipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u> Sta	atistical Iventory R	econciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No Sp	ill Prevention Equi	pment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	No Ta	nk Tightness Test	ing:	No	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	No US	T Internal Inspect	ions (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	Yes US	T Internal Lining I	nspections:	No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	<u>Yes</u> Ot	ner:	SafeGuard UST Inspection S	Services	UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	No				UST System Removal:	No
Environmental Service Firms					Other: FuelGuard fuel polishing / tank	cleaning
El Company			neultante:	No		
Emergency Cleanup - Spill/Release:	No US	T Compliance Co	noultaino.	. 10		
		T Compliance Co T Equipment Veri		No		
Emergency Cleanup - Spill/Release:	No US		fication:			
Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No US	T Equipment Veri	fication:	No		

UST Service Provider List (All) - Le	k Detection Testing Companies Only
--------------------------------------	------------------------------------

Company		Li	isting Submitted	1/5/2022	Area of state conducts work	
Johnson, Spellman & Associates, Inc.		Phone (770) 447-4555			Coastal (East of I-95): Yes	;
350 Research Ct.		Fax			Central (West of I-95 and East of I-77): Yes	
Suite 130		·				
Peachtree Corners, GA 30092	V	Vebsite			Mountains (West of I-77): Yes	i
Comp	liance Tes	ting and Monitoring			<b>UST Equipmment Service Contractors</b>	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Oper	rability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation S	ervices:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing	r.	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:		No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity	Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:		No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other: Er	ngineering- Design Sei	rvices	UST Piping/Sump Installation:	No
Line Tightness Testing:	No				UST System Removal:	No
Er	nvironment	al Service Firms			Other: Engineering-Design	Services
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:		<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:		<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:		No		
Oil and Solvent Recycling:	No	Other: E	ngineering-Design Sei	rvices		
Soil and Water Testing Lab:	No					
Company		Li	isting Submitted	12/20/2022	Area of state conducts work	
Jones Covey Group		Phone (888) 972-7581			Coastal (East of I-95): Yes	;
9595 Lucas Ranch Rd STE 100		Fax (909) 484-0300			Central (West of I-95 and East of I-77): Yes	;
Rancho Cucamonga, CA 91730		• •			Mountains (West of I-77): Yes	
	V	Vebsite			mountaine (reset et 111).	
Comp	liance Tes	ting and Monitoring			<b>UST Equipmment Service Contractors</b>	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Oper	rability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation S	ervices:	<u>Yes</u>	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing	:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:		<u>Yes</u>	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity /	Assessments):	<u>Yes</u>	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:		<u>Yes</u>	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	<u>Yes</u>	Other:			UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	<u>Yes</u>				UST System Removal:	No
Er	nvironment	al Service Firms			Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:		<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:		<u>Yes</u>		
LE : (0   1   10   10   10   10   10   10	NI-	Waste Disposal and Treatment:		No		
Environmental Engineer/Geologist Soil and GW Cleanu	NO	waste Disposal and Treatment.				
Oil and Solvent Recycling:	No No	Other:				

UST Service Provider List (All) - Leak Detection Testing Companies On	ly

Company		Listing Submitted	8/18/2020	Area of state conducts work	
Law Petroleum, Inc.	Pl	none (704) 573-3535		Coastal (East of I-95): Yes	
11025 Arlington Church Road		Fax (704) 573-3535		Central (West of I-95 and East of I-77): Yes	
Charlotte, NC 28227		,		Mountains (West of I-77): Yes	
	Web	site		mountaine (rest et 177).	
Comp	oliance Testing	g and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u> O	verfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u> S	tatistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No S	pill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	Yes Ta	ank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	<u>Yes</u> U	ST Internal Inspections (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u> U	ST Internal Lining Inspections:	<u>Yes</u>	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	Yes O	ther:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	<u>Yes</u>
Er	nvironmental S	Service Firms		Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u> U	ST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No U	ST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	ı No W	/aste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No O	ther:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	8/3/2020	Area of state conducts work	
MECO, Inc. of Florence	Pl	none (910) 223-0018		Coastal (East of I-95): Yes	
316 Raymond Street		Fax (910) 223-0022		Central (West of I-95 and East of I-77): Yes	
Fayetteville, NC 28301				Mountains (West of I-77): No	
	Web	osite www.mecoflorence.com		,	
Comp					
	oliance Testing	g and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:			Yes	UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration:	Yes
-	Yes O	g and Monitoring	Yes No		Yes Yes
Automatic Line Leak Detector Testing:	Yes O Yes S	g and Monitoring verfill Prevention Equipment Operability Check:		Dispenser Meter Repair/Calibration:	
Automatic Line Leak Detector Testing: Containment Sump Testing:	Yes O Yes S No S	g and Monitoring  Iverfill Prevention Equipment Operability Check: tatistical Iventory Reconciliation Services:	No	Dispenser Meter Repair/Calibration:  Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	Yes         O           Yes         S           No         S           No         T	g and Monitoring  Iverfill Prevention Equipment Operability Check: tatistical Iventory Reconciliation Services: pill Prevention Equipment Testing:	No <u>Yes</u>	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	<u>Yes</u> <u>Yes</u>
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Yes O Yes S No S No Ti	g and Monitoring  Iverfill Prevention Equipment Operability Check: tatistical Iventory Reconciliation Services: pill Prevention Equipment Testing: ank Tightness Testing:	No <u>Yes</u> No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	Yes Yes Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	Yes         O           Yes         S           No         S           No         T           No         U           Yes         U	g and Monitoring  Iverfill Prevention Equipment Operability Check: Itatistical Iventory Reconciliation Services: pill Prevention Equipment Testing: ank Tightness Testing: ST Internal Inspections (Integrity Assessments):	No <u>Yes</u> No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	Yes Yes Yes Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Yes         O           Yes         S           No         S           No         T           No         U           Yes         U	yerfill Prevention Equipment Operability Check: tatistical Iventory Reconciliation Services: pill Prevention Equipment Testing: ank Tightness Testing: ST Internal Inspections (Integrity Assessments): ST Internal Lining Inspections:	No <u>Yes</u> No No	Dispenser Meter Repair/Calibration:  Leak Detection Equipment Installation Servicing:  Spill Bucket Installation Repair:  UST Equipment Installation - Other:  UST Equipment Repair:  UST System Installation - Complete Systems:	Yes Yes Yes Yes Yes Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes         O           Yes         S           No         S           No         T           No         U           Yes         U           Yes         O	pand Monitoring Exercise Prevention Equipment Operability Check: Itatistical Iventory Reconciliation Services: Itatistical Iventory Reconciliation Services: Itatistical Iventory Reconciliation Services: Italian Services: Internal Inspections (Integrity Assessments): Internal Lining Inspections: Internal Lining Inspections: Italian Services: Internal Lining Inspections: Italian Services: Internal Lining Inspections: Int	No <u>Yes</u> No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	Yes Yes Yes Yes Yes Yes Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes O Yes S No S No Ti No U Yes U Yes O No	pand Monitoring Exercise Prevention Equipment Operability Check: Itatistical Iventory Reconciliation Services: Itatistical Iventory Reconciliation Services: Itatistical Iventory Reconciliation Services: Italian Services: Internal Inspections (Integrity Assessments): Internal Lining Inspections: Internal Lining Inspections: Italian Services: Internal Lining Inspections: Italian Services: Internal Lining Inspections: Int	No <u>Yes</u> No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes O Yes S No S No Ti No U Yes U Yes O No No U Yes O No O  Invironmental S	yerfill Prevention Equipment Operability Check: tatistical Iventory Reconciliation Services: pill Prevention Equipment Testing: ank Tightness Testing: ST Internal Inspections (Integrity Assessments): ST Internal Lining Inspections: other:	No Yes No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Er Emergency Cleanup - Spill/Release:	Yes O Yes S No S No Ti No U Yes U Yes O No No U No U No U No U No U	pand Monitoring Exercise Prevention Equipment Operability Check: Itatistical Iventory Reconciliation Services: Ipill Prevention Equipment Testing: Internal Inspections (Integrity Assessments): Internal Lining Inspections: Internal Lining Inspections: Internal Consultants:	No Yes No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Yes O Yes S No S No Ti No U Yes U Yes O No O Invironmental S No U No U No U No W	pand Monitoring Exercise Prevention Equipment Operability Check: Itatistical Iventory Reconciliation Services: Itatistical Iventory Reconciliation Services: Itatistical Iventory Reconciliation Services: Itatistical Iventory Reconciliation Services: Internal Prevention Equipment Testing: Internal Inspections: Internal Inspections (Integrity Assessments): Internal Lining Inspections: Internal Lining Inspections: Internal Compliance Consultants: Internal Inspections: Internal Inspec	No Yes No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes

UST Service Provider List (All) - Le	k Detection Testing Companies Only
--------------------------------------	------------------------------------

Company		Listing Submitted	12/30/2021	Area of state conducts work	
Petroleum Equipment and Service, Inc.	Pho	one (704) 335-8801		Coastal (East of I-95): No	
4125 Sinclair Street		Fax (704) 342-1672		Central (West of I-95 and East of I-77): Yes	
PO Box 1949				Mountains (West of I-77): Yes	
Denver, NC 28037	Webs	ite <u>www.petroleumequipment.net</u>		moditalits (West 61177). 163	
Comp	oliance Testing	and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u> Ov	erfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:		itistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No Sp	Il Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:		nk Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	No US	T Internal Inspections (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	Yes US	T Internal Lining Inspections:	<u>Yes</u>	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	Yes Oth	ner:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	<u>Yes</u>
Er	nvironmental Se	ervice Firms		Other:	
Emergency Cleanup - Spill/Release:	No US	T Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No US	T Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No Wa	ste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	No Oth	ner:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	8/18/2020	Area of state conducts work	
Petroleum Service & Calibration, Inc.	Dh	(704) 400 4674		0 (1/5 (105) )/	
	FIII	one (704) 489-1671		Coastal (East of I-95): Yes	
7973 Vista View Drive		, ,			
,				Central (West of I-95 and East of I-77): Yes	
7973 Vista View Drive		Fax (704) 489-1672			
7973 Vista View Drive Sherrills Ford, NC 28673	Webs	Fax (704) 489-1672		Central (West of I-95 and East of I-77): Yes	
7973 Vista View Drive Sherrills Ford, NC 28673	Webs	ite www.petroleumtanktesting.com	<u>Yes</u>	Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): No	Yes
7973 Vista View Drive Sherrills Ford, NC 28673  Comp Automatic Line Leak Detector Testing: Containment Sump Testing:	Webs  bliance Testing  Yes Ov	Fax (704) 489-1672  ite www.petroleumtanktesting.com  and Monitoring	Yes No	Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): No  UST Equipmment Service Contractors	Yes Yes
7973 Vista View Drive Sherrills Ford, NC 28673  Comp Automatic Line Leak Detector Testing:	Webs  bliance Testing  Yes Ov  Yes Sta	ite www.petroleumtanktesting.com  and Monitoring erfill Prevention Equipment Operability Check:		Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration:	
7973 Vista View Drive Sherrills Ford, NC 28673  Comp Automatic Line Leak Detector Testing: Containment Sump Testing:	Webs  Dliance Testing  Yes Ov  Yes Sta  No Sp	ite www.petroleumtanktesting.com and Monitoring erfill Prevention Equipment Operability Check: utistical Iventory Reconciliation Services:	No	Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): No  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration:  Leak Detection Equipment Installation Servicing:	<u>Yes</u>
7973 Vista View Drive Sherrills Ford, NC 28673  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	Webs  Dliance Testing  Yes Ov  Yes Sta  No Sp  No Ta	ite www.petroleumtanktesting.com  and Monitoring erfill Prevention Equipment Operability Check: tistical Iventory Reconciliation Services: Il Prevention Equipment Testing:	No <u>Yes</u>	Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): No  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	<u>Yes</u> No
7973 Vista View Drive Sherrills Ford, NC 28673  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	Webs  bliance Testing  Yes Ov  Yes Sta  No Sp  No Ta  Yes US	ite www.petroleumtanktesting.com and Monitoring erfill Prevention Equipment Operability Check: distical Iventory Reconciliation Services: Il Prevention Equipment Testing: nk Tightness Testing:	No <u>Yes</u> <u>Yes</u>	Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): No  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	<u>Yes</u> No No
7973 Vista View Drive Sherrills Ford, NC 28673  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	Webs  pliance Testing  Yes Ov  Yes Sta  No Sp  No Ta  Yes US  Yes US	ite www.petroleumtanktesting.com  and Monitoring  erfill Prevention Equipment Operability Check: tistical Iventory Reconciliation Services: Il Prevention Equipment Testing: nk Tightness Testing: T Internal Inspections (Integrity Assessments):	No <u>Yes</u> <u>Yes</u> No	Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): No  UST Equipment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	Yes No No No
7973 Vista View Drive Sherrills Ford, NC 28673  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Webs  Dliance Testing  Yes Ov  Yes Sta  No Sp  No Ta  Yes US  Yes US	ite www.petroleumtanktesting.com  and Monitoring erfill Prevention Equipment Operability Check: tistical Iventory Reconciliation Services: Il Prevention Equipment Testing: hk Tightness Testing: T Internal Inspections (Integrity Assessments): T Internal Lining Inspections:	No <u>Yes</u> <u>Yes</u> No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes No No No No
7973 Vista View Drive Sherrills Ford, NC 28673  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Webs  Dliance Testing  Yes Ov  Yes Sta  No Sp  No Ta  Yes US  Yes US  Yes Ott	ite www.petroleumtanktesting.com  and Monitoring  erfill Prevention Equipment Operability Check: tistical Iventory Reconciliation Services: Il Prevention Equipment Testing: hk Tightness Testing: T Internal Inspections (Integrity Assessments): T Internal Lining Inspections: her:	No <u>Yes</u> <u>Yes</u> No	Central (West of I-95 and East of I-77): Yes  Mountains (West of I-77): No  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	Yes No No No No No
7973 Vista View Drive Sherrills Ford, NC 28673  Comp  Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Webs  pliance Testing  Yes Ov  Yes Sta  No Sp  No Ta  Yes US  Yes US  Yes Ott  Yes Ott  Yes  nvironmental Se	ite www.petroleumtanktesting.com  and Monitoring  erfill Prevention Equipment Operability Check: tistical Iventory Reconciliation Services: Il Prevention Equipment Testing: hk Tightness Testing: T Internal Inspections (Integrity Assessments): T Internal Lining Inspections: her:	No <u>Yes</u> <u>Yes</u> No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes No No No No No
7973 Vista View Drive Sherrills Ford, NC 28673  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Webs  Dliance Testing  Yes Ov  Yes Sta  No Sp  No Ta  Yes US  Yes US  Yes Ott  Yes  No US	ite www.petroleumtanktesting.com  and Monitoring  erfill Prevention Equipment Operability Check: tistical Iventory Reconciliation Services: Il Prevention Equipment Testing: nk Tightness Testing: T Internal Inspections (Integrity Assessments): T Internal Lining Inspections: ner:	No Yes Yes No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes No No No No No
7973 Vista View Drive Sherrills Ford, NC 28673  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Er Emergency Cleanup - Spill/Release:	Webs  Dliance Testing  Yes Ov Yes Sta No Sp No Ta Yes US Yes US Yes Ott Yes  No US No US No US	ite www.petroleumtanktesting.com  and Monitoring  erfill Prevention Equipment Operability Check: titistical Iventory Reconciliation Services: Il Prevention Equipment Testing: the Tightness Testing: T Internal Inspections (Integrity Assessments): T Internal Lining Inspections: ther:  Ervice Firms T Compliance Consultants:	No Yes Yes No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes No No No No No
7973 Vista View Drive Sherrills Ford, NC 28673  Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:  Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Webs  pliance Testing  Yes Ov  Yes Sta  No Sp  No Ta  Yes US  Yes US  Yes Ott  Yes  No US  No US  No US  No US  No US	ite www.petroleumtanktesting.com  and Monitoring erfill Prevention Equipment Operability Check: distical Iventory Reconciliation Services: Il Prevention Equipment Testing: the Tightness Testing: T Internal Inspections (Integrity Assessments): T Internal Lining Inspections: ther:  Ervice Firms T Compliance Consultants: T Equipment Verification:	No Yes Yes No No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No  UST Equipmment Service Contractors  Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes No No No No No

UST Service Provider List (All) - Le	k Detection Testing Companies Only
--------------------------------------	------------------------------------

Company		· /	_isting Submitted	5/14/2021	Area of state conducts work	
Petroleum Solutions Inc.	Pł	one (919) 605-1979			Coastal (East of I-95): Yes	
3012 Whitehart Ln.		Fax (919) 773-1704			Central (West of I-95 and East of I-77): Yes	
819 Purser Drive		14x (313) 113-110 <del>4</del>				
Raleigh, NC 27606	Web	site <u>www.petroleumsolutio</u>	nsinc.net		Mountains (West of I-77): No	
Comp	oliance Testing	and Monitoring			<b>UST Equipmment Service Contractors</b>	
Automatic Line Leak Detector Testing:	No O	verfill Prevention Equipment Ope	erability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	Yes St	atistical Iventory Reconciliation	Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No S	oill Prevention Equipment Testing	g:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	No Ta	ank Tightness Testing:		No	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	No U	ST Internal Inspections (Integrity	Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	No U	ST Internal Lining Inspections:		No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	No O	ther:			UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	No				UST System Removal:	<u>Yes</u>
Er	nvironmental S	ervice Firms			Other:	
Emergency Cleanup - Spill/Release:	No U	ST Compliance Consultants:		No		
Environmental Engineer/Geologist - Site Checks:	No U	ST Equipment Verification:		<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	No W	aste Disposal and Treatment:		No		
Oil and Solvent Recycling:	No O	ther:				
Soil and Water Testing Lab:	No					
Company			_isting Submitted	12/30/2021	Area of state conducts work	
Precision Tank Service	Ph	one (704) 892-8600			Coastal (East of I-95): Yes	
737 Zimmer Road		Fax (704) 892-8711			Central (West of I-95 and East of I-77): Yes	
Fort Mill , SC 29707		(101) 002 0111			Mountains (West of I-77): Yes	
	Web	site <u>www.precisiontankser</u>	<u>vice.com</u>		Mountains (West of 1-77). Tes	
Comp	oliance Testing	and Monitoring			<b>UST Equipmment Service Contractors</b>	
Automatic Line Leak Detector Testing:	Yes O	verfill Prevention Equipment Ope	erability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	Yes St	atistical Iventory Reconciliation	Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No S	oill Prevention Equipment Testing	g:	<u>Yes</u>	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No Ta	ank Tightness Testing:		<u>Yes</u>	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	Yes U	ST Internal Inspections (Integrity	Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	Yes U	ST Internal Lining Inspections:		No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	Yes O	ther:			UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>				UST System Removal:	No
S S					Other:	
	nvironmental S	ervice Firms				
		ST Compliance Consultants:		Yes		
Er	No U			<u>Yes</u> No		
Emergency Cleanup - Spill/Release:	No Us	ST Compliance Consultants:				
Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No U: No U: No W	ST Compliance Consultants: ST Equipment Verification:		No		

UST Servi	ce Provi	der List (All) - Leak Detection	Testing (	Companies Only	
Company		Listing Submitted	12/30/2021	· · · · · · · · · · · · · · · · · · ·	
Superior Services		Phone (828) 698-6286		Coastal (East of I-95): Yes	;
PO Box 982		Fax (828) 698-6294		Central (West of I-95 and East of I-77): Yes	3
Hendersonville, NC		,		Mountains (West of I-77): Yes	
	We	ebsite <u>www.superiorservices.com</u>			
Com	pliance Testi	ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	<u>Yes</u>	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other: Repair and lining, AST Inspections, Repairs and	Lining	UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	No
E	nvironmenta	Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	ı No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	12/30/2021	Area of state conducts work	
Terraquest Environmental Consultants, P.C.		Phone (919) 563-9091		Coastal (East of I-95): Yes	;
100 E. Ruffin Street		Fax (919) 563-9095		Central (West of I-95 and East of I-77): Yes	3
Mebane, NC 27302	W	ebsite www.terraguestpc.com		Mountains (West of I-77): Yes	<b>S</b>
Com		ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:		Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:		Statistical Iventory Reconciliation Services:	No No	Leak Detection Equipment Installation Servicing:	No No
Corrosion Protection Design Experts:	<u>Yes</u> No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Repairs.  Corrosion Protection System Testing:		UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:	. 10	UST Piping/Sump Installation:	No
reak Detection Monitoring Services	INO	Ciner		L UST PIDINO/SUMD INSTALIATION	INO

Oil and Solvent Recycling:

Soil and Water Testing Lab:

Emergency Cleanup - Spill/Release:

Environmental Engineer/Geologist - Site Checks:

Environmental Engineer/Geologist Soil and GW Cleanu Yes

**Environmental Service Firms** 

Other:

<u>Yes</u>

<u>Yes</u>

No

<u>Yes</u>

**UST Compliance Consultants:** 

Waste Disposal and Treatment:

**UST** Equipment Verification:

Other:

No

No

<u>Yes</u>

UST Service Provider List (All) - Le	k Detection Testing Companies Only
--------------------------------------	------------------------------------

Company		01 2101 (711	Listing Submitted	8/13/2020	Area of state conducts work	
Unified Services of Texas	P	hone (817) 48°			Coastal (East of I-95): Yes	
2110 Greenbriar dr.		Fax			Central (West of I-95 and East of I-77): Yes	
Southlake, TX 76092		- 4/4			Mountains (West of I-77): Yes	
	Web	osite <u>ustfuel.co</u>	<u>om</u>		Mountains (West of 1-17). Tes	
Comp	oliance Testin	g and Monitorin	ng		<b>UST Equipmment Service Contractors</b>	
Automatic Line Leak Detector Testing:	<u>Yes</u>	verfill Prevention I	Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	Yes S	tatistical Iventory I	Reconciliation Services:	<u>Yes</u>	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:		pill Prevention Equ		<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:		ank Tightness Tes		<u>Yes</u>	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:			ctions (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	ST Internal Lining	Inspections:	<u>Yes</u>	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	<u>Yes</u>	other:			UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	<u>Yes</u>				UST System Removal:	<u>Yes</u>
Er	nvironmental	Service Firms			Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	ST Compliance C	onsultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	Yes L	ST Equipment Ve	rification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u> V	aste Disposal and	d Treatment:	No		
Oil and Solvent Recycling:	<u>Yes</u>	ther:				
Soil and Water Testing Lab:	No					
Company			Listing Submitted	7/14/2022	Area of state conducts work	
VALLEY TANK TESTING	P	hone (813) 67	1-9065		Coastal (East of I-95): Yes	
451 APOLLO BEACH BOULEVARD		Fax (866) 328			Central (West of I-95 and East of I-77): Yes	
APOLLO BEACH, FL 33572		1 dx (000) 020	3 37 30			
	Web	osite <u>WWW.V</u>	ALLEYTANK.COM		Mountains (West of I-77): Yes	
Comp	oliance Testin	g and Monitorin	ng		<b>UST Equipmment Service Contractors</b>	
Automatic Line Leak Detector Testing:	<u>Yes</u>	verfill Prevention I	Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u> S	tatistical Iventory I	Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No S	pill Prevention Equ	uipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No T	ank Tightness Tes	sting:	<u>Yes</u>	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	<u>Yes</u>	ST Internal Inspec	ctions (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	<u>Yes</u>	IST Internal Lining	Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	<u>Yes</u>	other:			UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>				UST System Removal:	No
		Convice Firms			Other:	
Er	nvironmental	service Firms				
Emergency Cleanup - Spill/Release:		ST Compliance C	onsultants:	No		
	No L			No No		
Emergency Cleanup - Spill/Release:	No L	ST Compliance C	rification:			
Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No L No L No V	ST Compliance C ST Equipment Ve	rification:	No		

## UST Service Provider List (All) - Leak Detection Testing Companies Only

Company		Listing Submitted	d 2/5/2021	Area of state conducts work	
Wildco PES	Phone	(603) 935-9330		Coastal (East of I-95): Yes	3
440 Harvey Rd	Fax			Central (West of I-95 and East of I-77): Yes	3
497 Lendall Lane Fredericksburg VA 22405 Manchester, NH 3103	Website	WILDCOPES.COM		Mountains (West of I-77): No	
Comp	liance Testing and	l Monitoring		<b>UST Equipmment Service Contractors</b>	
Automatic Line Leak Detector Testing:	Yes Overfill	Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	Yes Statisti	cal Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No Spill Pr	revention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	No Tank T	ightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	Yes UST In	ternal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	Yes UST In	ternal Lining Inspections:	No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	Yes Other:			UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	<u>Yes</u>
En	vironmental Servi	ce Firms		Other:	
Emergency Cleanup - Spill/Release:	No UST C	ompliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No UST E	quipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	No Waste	Disposal and Treatment:	No		
Oil and Solvent Recycling:	No Other:				
Soil and Water Testing Lab:	No				